



Federal Aviation Administration

Memorandum

Date: JUL 29 2013

To: Kim O. Davies, Manager, Flight Standards Southern Region, ASO-230

From: Steven W. Douglas, Manager, Aircraft Maintenance Division, AFS-300 *SWD*

Prepared by: Carlos A. Quiles, Aviation Safety Inspector, AFS-340

Subject: Clarification Around Training Requirements

This memo is in response to your memo, dated June 24, requesting clarification of training requirements. Your question is, "Does a repair station training program, as required by part 145.163 (b) (referencing language in part 65.101 (a) (2) & (5) (i)), requires the training be to a specific part number or just for the particular task?"

Based on the review of applicable rules and guidance, we have determined that if a person understands the manufacturers' current instructions and maintenance manuals, that person is not required to have specific part number/dash number articles.

If you have any questions, please contact Darcy Reed, Manager of the Repair Station Branch, AFS-340, at (202) 385-4277.